Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: P EVITT 154-98-13-12-1-3H3

Field Name: TRUAX Well File #: 25511

Date Incident: 10/22/2015 Time Incident: 02:00 Facility ID Number:

County: WILLIAMS Twp: 154 Rng: 98 Sec: 12 Qtr: SW SE

Location Description:

Submitted By: Corissa Zimmer Received By:

Contact Person: Corissa Zimmer

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.2 MileDistance Nearest Water Well:0.2 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels			8	barrels
Brine	8	Barrels			8	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/19/2016 Clean Up Concluded: 10/25/2015

Risk Evaluation:
None noted

Areal Extent:

Potential Environmental Impacts:

None noted

Action Taken or Planned:

Whiting will ensure there is more awareness and preventative maintenance regarding potential spills resulting from gasket issues on treaters.

Wastes Disposal Location: Recovered wastes will be disposed of at an approved facility.

Agencies Involved:

Updates

Date: 10/22/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to a treater leak, remained on location according to the report. NDIC retains oversight.